




RetroRoof™ De-icing – Estimate Guide Sheet

Select Panel Lengths to Create Similar Layouts



Quick Reference Chart

Integrated-Existing Roof Electric	Premier Switch	Gold Controller
PROBLEM SPOTS Problem plus 1' to 2' beyond; both sides	✓	OPTIONAL
ABOVE WINDOWS AND DOORS 1' to 2' beyond	✓	OPTIONAL
EAVES North Side: 3 courses (rows) underneath shingle exposure; 6" from rake edge (at power supply)	N/A	✓
GUTTER (All Hard Wired)	✓	✓
VALLEYS Re-Roof/NEW	✓	OPTIONAL



For more detailed information contact a Warmzone roof de-icing expert at 888.488.9276.